


Small Site Erosion & Sediment Control in Tauranga City



- 
- Background
 - Where are we now
 - Legislation
 - Progress Made
 - Issues: Old & New
 - Future Direction

Background

- Reason for Project
- Education
- Response
- Non Compliance
- Issues



Where are we now?

- Env. Monitoring led process
- Building Inspectors limited input
- Education plus Enforcement
- Growing Database




Legislation

- City Plan – Earthworks & sect. 9 (3) RMA (1991)
- Consent Application
- Building Code
- Stormwater Bylaw (2015)



Progress Made


- Controls Evident on most Sites
- Reduction in Sediment Control CCMs
- Routine E & S Control visit for each Consent



Issues: Old & New

14/11/2016, 1:55:18 PM
-37.76380488,176.10811246

- Pre Application
- Earthworks
- Inadequate C
- Tracking
- Sub Contractor
- Landscaping
- Difficult Sites



14/11/2016, 1:55:18 PM
-37.76380488,176.10811246

Future Direction

- New Tech Opportunities
- Inspections
- Extra Fees
- Increase in Enforcement for Non-Compliance



InspectIT – Taura... 4+
Touchtech Ltd >


OPEN

Details

Reviews

Related

iPhone



Questions

